



Recall Airbags Are Available - Takata - Saab 93/95 - Ordering Procedure

Attention: Parts Managers. Service Managers & General Managers:

- Parts are available - you can begin placing limited orders today as needed.
- Register here - [Takata Airbag Recall Webinar - Parts are Available - Monday, 1:30 PM - 2:30 PM EDT](#)

Owner Communications:

- Zone "A" HAH (High Absolute Humidity) - **Owner letters are scheduled to mail March 17th** (zone map Pg. 2).
 - **Note:** Notifications will be sent to owners whose vehicles were at one time registered in Zone "A"
 - These owner may now be registered in any other state or zone.
- Zone "B & C" NON-HAH - vehicle owners will receive notification an estimated 2-4 weeks after the Zone "A" owners.
- Zone "A, B & C - Approximately 1,500 model year 2010 and 2011 Saab 9-3 vehicle owners may not receive notification for several weeks.

Owner Notification Letters **are not required:**

- **OSC's may perform recalls on both HAH and Non-HAH vehicles even if the owner has not received a Notice Letter**
- **Please be sure to check VIN history for open recalls**

Recall Numbers – Area – Model - Year - Volume

- | | | | | |
|---------|--------------------|-----------------------|----------------------|---------------|
| • 15043 | HAH (Zone A) | Saab 93 -2006 to 2011 | Saab 95 2006 to 2009 | Volume 30,863 |
| • 15041 | Non-HAH (Zone B&C) | Saab 93 -2006 to 2011 | Saab 95 2006 to 2009 | Volume 70,914 |

Part & Bulletin Information:

- Part Number – 39095647
- OSC Net Price – \$187.50
- [Click for - GM-Saab Recall Bulletin 15043 - 28811](#)
- [Click for - GM-Saab Recall Bulletin 15041 - 28810](#)

Order System Rules:

- **Maximum 4 pieces per order**
- Ground orders only will be accepted
- All orders will incur a \$45 ground Hazmat Fee regardless of the quantity ordered (from 1 to a maximum 4 pieces)

Hazmat Allowance – Per Claim:

- The Standardized Hazmat Fee per vehicle claim will be \$11.25 (for 15043 & 15041 driver's airbags only)
- **Choosing to order less than 4 pieces will NOT increase the \$11.25 Standardized Hazmat Fee claim allowance.**
- There will be an unrecoverable Hazmat cost penalty if you order less than 4 pieces per order
- If an exception is needed for lower volume OSC's, requests will be reviewed on a case by case basis
- Please be sure to notify your Warranty Administrator about the Standardized Hazmat Fee

Order Procedures:

- It is **highly recommended** that you always order 4 airbags per order
- Please order only two weeks estimated demand
- Parts are not eligible for the Aero parts return.

NOTE: If you have any questions, please contact your Sales Representative or the Parts Help Line.



2550 Brodhead Rd, Suite 100 | Bethlehem, PA 18020

GM Takata Recall – Zone Map – Saab 93 & 95

